

Sponsors and Collaborators




Lessons Learnt and Findings from BIRDS5-FTA

08/03/2023

- Status of BIRDS5 satellites
- Satellites operation report
- Possible causes of failure
- FTA tests conducted and the obtained results
 - Analysis of the results
- Conclusion of FTA
- Lessons learnt and recommendation for design improvement

BIRDS 5 Status

- ❑ BIRDS 5 satellites were deployed on the 2nd of December 2022



<https://www.youtube.com/watch?v=oWabTGG4plc>

BIRDS 5 In Orbit Status

Look4Sat APP

Name	ID	Satellite	Altitude (km)
1998-067UL	54534	Taka	368
1998-067UM	54535	PearlAfricaSat-1	358
1998-067UN	54536	ZIMSAT1	373
ISS (ZARYA)	25544	ISS	415

No signal received from all the three satellites

1998-067UN Id:54536

AOS - 179.1° Altitude: 373 km 72.5° - LOS

20:51:59 - Wed Elevation: 9.8° Wed - 21:00:05

1998-067UP Id:54537

AOS - 201.8° Altitude: 368 km 58.9° - LOS

21:23:53 - Wed Elevation: 24.6° Wed - 21:33:26

1998-067UL Id:54534

AOS - 206.1° Altitude: 368 km 56.7° - LOS

21:31:05 - Wed Elevation: 30.0° Wed - 21:40:47

1998-067UM Id:54535

AOS - 208.9° Altitude: 358 km 55.2° - LOS

21:33:08 - Wed Elevation: 34.0° Wed - 21:42:50

Satellites tracking

- Kyutech GS (main)
- BIRDS GS network
- SATNOGS
- Wakayama GS (12 m, 30 dBi Antenna Gain)


Satellite	CW Beacon	UHF Uplink	UHF Downlink	Remark
PearlAfricaSat-1	X	X	X	<input type="checkbox"/> No CW <input type="checkbox"/> No uplink success <input type="checkbox"/> No downlink success
TAKA	X	X	X	
ZIMSAT-1	X	X	X	

 Uplink Commands send:

- Force CW
- Erase flash memories

<input checked="" type="radio"/>	Successful
<input type="checkbox"/>	Not Successful

Possible Causes of Failure




□ Others:

- Design issues? Individual hardware issues? Software issues? Workmanship issues? Fault parts?

A. BIRDS5 Operation Software

- EM satellite is functional
- KITSUNE with the same frequency can be detected.
- BIRDS-5S working properly



B. Wakayama University and BIRDS Network Ground Stations Hardware

- Kitsune CW can be heard
- No signal from BIRDS satellites



❖ Wrong settings: **Denied**


2. Satellites were not Activated

A. RBF pins were not removed

- ❑ **Denied:** RBF pins removed by JAXA



RBF pins returned to Kyutech




No RBF pins seen in JAXA's video

[Small Satellites Deployment J-SSOD#23 from "Kibo" \(BIRDS-5, and SpaceTuna1\) 「きぼう」から超小型衛星の放出 - YouTube](#)

B. Jumper pins (J15) on the FAB dropped during vibration

- ❑ **Denied:**
 - ❑ Glued during assembly
 - ❑ After vibration the satellites functioned




J15 highlighted

C. Deployment switches failed due to:

I. Design changes

- Position changed from Birds4




	BIRDS-4	BIRDS-5	Futaba
Depression length of the switch when the satellite is stored in the J-SSOD	1.5mm	1.3mm	1.2mm
Period of being stored from handover to release	5.5 months (2020/10/01 - 2021/3/14)	6 months(10%↑) 2022/6/7 - 2022/12/2	5.5 months 2022/02/24- 2022/08/12

□ **Unlikely**


=>Futaba design was in more severe condition

II. *Electrical Chattering*

- ❑ Likely occur **during launch and deployment**
- ❑ Dangers
 - Can affect Reset-PIC
 - Can affect powerlines
- ❑ Effects tested under atmosphere and vacuum (TVT) conditions



- ☐ Structural Design of BIRDS5 Satellite
 - 3 Deployment switches





Dep1	Dep2	Dep3
ON	ON	Chattering
ON	Chattering	ON
Chattering	ON	ON

- ❑ Simulate rapid turning on/off of satellite:
 1. Program BIRDS-5S Satellite with TAKA FM Code
 2. Fully Erase Satellite
 3. Rapidly turn on/off satellite using deployment switch toggling
 4. Observe data collection and verify normal
 5. Repeat 3–4

Parameters	Test 1	Test 2	Test 3
FAB data	Normal	Normal	Normal
RESET data	Normal	Normal	Normal
Flags and addresses	Normal	Normal	Normal
CW	Normal	Normal	Normal


Chattering Test: During TVT



Deployment switch x 3



Dep1	Dep2	Dep3
ON	ON	Chattering
ON	Chattering	ON
Chattering	ON	ON

TVT(1&2) Thermal Cycles



Because of other satellite operations at Kyutech

□ 3 cycles and 2hr hot soak



TVT2

	sec	min	hour	day
1	333303000	3	0	0
2	333303000	3	0	0
3	333303000	3	0	0
4	333320010	32	1	0
5	333302030	2	3	0
6	333320040	32	4	0
7	333302060	2	6	0
8	333320070	32	7	0
9	333302090	2	9	0
10	3333200a0	32	10	0
11	3333020c0	2	12	0
12	33331f0d0	31	13	0
13	3333010f0	1	15	0
14	33331f1000	31	16	0
15	3333011200	1	18	0
16	33331f1300	31	19	0
17	3333011500	1	21	0
18	33331f1600	31	22	0
19	3333011800	1	24	0
20	33331f1900	31	25	0
21	3333011b00	1	27	0
22	333302000	2	0	0
23	333302000	2	0	0
24	333302000	2	0	0
25	333320010	32	1	0


1st turn on
2nd turn on
3rd turn on

Longest ON time: 27 mins

4th turn on
5th turn on
6th turn on


Chattering

Turn on SAT
in chamber





- TVT1 Results : **Chattering not successful**, No CW, No FM, Sat OFF
- TVT2 Results: **Chattering was successful**, No CW, No FM, Battery damaged, Sat ON

- 2 cycles and 1hr hot soak



☐ CW received, FM command also confirmed, chattering was successful



Parameters	TVT1	TVT2	Test 3
FAB data	Not Confirmed	Normal	Normal
RESET data	Not Confirmed	Normal	Normal
Flags and addresses	Not Confirmed	Normal	Normal
CW	Not Confirmed	Not Confirmed	Normal

Unlikely that failure was due to electrical chattering

III. Mechanical Chattering

□ Due to vibration

➤ Dangers


- ✓ Physical damage of deployment switches

➤ Test condition1 with 46.6N:



- ✓ Random and sine burst vibration
- ✓ Total force to the four rails: 19Kg(186.6N)
- ✓ Functionality was okay hence **unlikely**

➤ Test condition2 with 0.2mm room:

- ✓ Random and sine burst vibration
- ✓ Functionality was okay hence **unlikely**





Test condition1




Test condition2


Kyutech Video of Mechanical Chattering (0.2mm Room)



D. Satellites damaged by rocket vibration




NG-17 (KITSUNE)
→Looks good



NG-18 (BIRDS-5)

- Direction was wrong after booster separation
- It has a spike at the time of separation
- Cygnus Cargo ship failed to deploy one of the solar array



Only one solar panel deployed

In a statement late Nov. 9, Northrop Grumman blamed the failed deployment of the array on debris from the launch. “During a rocket stage separation event, debris from an Antares acoustic blanket became lodged in one of the Cygnus solar array mechanisms, preventing it from opening,” said Cyrus Dhalla, vice president and general manager of tactical space systems at Northrop Grumman. The company did not explain how the debris got into the mechanism, something the company has not reported happening on previous Cygnus launches.



2. Satellites were not Activated Continue... Damaged with Rocket Vibration

- The satellite pod was covered by cushion.
- Vibration level in the rocket is much smaller than the vibration test we conduct
- Satellites were damaged by launch vibration?


=> **Unlikely**

E. Battery Failure

	2022/5/2	2022/5/20
ZIMSAT-1	4.21V	3.99V
TAKA	4.21V	4.02V
PearlAfricaSat-1	4.2V	3.99V


- In 18 days battery voltage decreased by 0.2V
- Estimated capacity decrease of 3.5% is expected
 - Estimated from battery thermal test.
- Assuming 3.5% in 18 days => 35% decrease in 6 months
- Worst Case 50% capacity decrease => 3.6V
 - Can the satellite turn ON at 3.6V?

Battery Thermal Test: 1 Cell Discharge Rate



Battery Test


Battery Recovery: Sun Simulator Results



2.51V Battery Voltage

- ❑ At 50% battery capacity, satellite was tested for
 - Activation and
 - Antenna deployment
- ❑ Condition
 - Vacuum: TVT
 - Atmosphere temperature: Clean room
- ❑ Results
 - No CW
 - Antenna did not deploy
 - Battery was damaged by TVT
- ❑ Solution
 - Charge satellite battery with sun simulator
 - After 38 mins, antenna deployed and CW heard

Battery Recovery test



❑ Failure due to battery is therefore **denied**

3. Satellites were activated but failed to start the Transmitter

A. Malfunctioning

- Transceiver malfunctioning experienced at FM
- Reason: Transceiver design change
- Solution: R13 and R14 removed
- Unlikely**
 - Long duration test were good
 - Transceiver purchased on different batches
 - Cannot occur on all the three satellites



Summary Transceiver Malfunctioning

Transceiver Mounted on	Problem	Solution	Status of the Flight Model
PealAfricaSat-1	<input type="checkbox"/> High Power Draw <input type="checkbox"/> No Reset Data	<input type="checkbox"/> Removed R13 and 14	<input type="checkbox"/> Normal power draw <input type="checkbox"/> Reset data obtained <input type="checkbox"/> Downlink and uplink were OK
ZIMSAT-1	<input type="checkbox"/> High Power Draw <input type="checkbox"/> No Reset Data	<input type="checkbox"/> Removed R13 and 14	<input type="checkbox"/> Normal power draw <input type="checkbox"/> Reset data obtained <input type="checkbox"/> Downlink and uplink were OK
TAKA	<input type="checkbox"/> No problem	<input type="checkbox"/> N/A	<input type="checkbox"/> Normal power draw <input type="checkbox"/> Reset data obtained <input type="checkbox"/> Downlink and uplink were OK
BIRDS-5S	<input type="checkbox"/> High Power Draw <input type="checkbox"/> No Reset Data <input type="checkbox"/> No CW beacons	<input type="checkbox"/> Removed R13 and 14 <input type="checkbox"/> Send for repair with Kojima San	<input type="checkbox"/> Normal power draw <input type="checkbox"/> Reset data obtained <input type="checkbox"/> Downlink and uplink were OK

3. Satellites were activated but failed to start the Transmitter

B. Low battery power

- Denied** : CW can be emitted when the satellite recovers

C. Main-PIC and COMPIC errors **unlikely**

D. Reset PIC fails turn on COMPIC and/or Tx after 30 mins

- Unlikely** -no malfunctioning was found after chattering test and low battery test

3. Satellites were activated but failed to start the Transmitter

E. Main PIC fails to turn on due to low OCP threshold setting (150mA)

- Unlikely**- not seen on the ground test

F. Reset PIC malfunctioning

- Observed in BIRDS-5 due to transceiver
 - Satellites could not receive reset data
 - Satellite could not reset
- The problem was solved and never encountered again nor reproduced
- Unlikely but open**

□ Comparison of BIRDS3, 4, and KITSUNE

- BIRDS-3 Reset PICs worked for the entire period of their operations
- BIRDS-4 Reset PIC malfunctioned after the first CW and lost the time-counting capability and the UART communication with Main PIC.
- KITSUNE reset PIC worked for almost 1 year in orbit
 - ✓ During SPATIUM-2 development on the ground, It was observed that Reset PIC had a malfunction of time counter .

Difference Lots of BIRDS4, KITSUNE and BIRDS5 components

- DC/DC convertor
- **PICS (RESET, COMPIC, FABPIC)**
- OCP
- MOSFET switch (UNREG1, UNREG2)
- Crystal
- Clock Oscillator

Parts Number	Usage	BIRDS3	BIRDS4	KITSUNE	BIRDS5	MO-1	ChibaTech
PIC16F1789-I/MV	Reset-PIC, COM-PIC, FAB-PIC	2018.5	5 from 2018.5				
			4 from 2019.9				
				2020.4_25int ake			
					3 from 2020.4_9int ake		
					15 from 2021.8	2021.8	2021.8 or 2022.4

- ❑ **Unlikely but open** because failure could not be reproduced
 - => Chattering of deployment switch was expected to generate some noise
 - => No effects observed on the reset PIC

Long Duration Test Report

A. Programming errors

B. COMPIC errors

Unlikely


- Long duration test results were okay
- Errors never detected during operations

Transceiver Mounted on	Uplink	Downlink		
	GMSK	GMSK	CW Morse	Downlink Successful on the Following Missions
<input type="checkbox"/> PEARLAFRICASAT-1 <input type="checkbox"/> TAKA <input type="checkbox"/> ZIMSAT-1	OK	OK	OK	<ul style="list-style-type: none"> • Multispectral Camera • Store and Forward Mission • APRS (Automatic Packet Reporting System) Mission • Image Classification • ADCS (Attitude Determination and Control System) and Attitude Visualization: High Sampling and Housekeeping Data

4. Transmitter not Emitting CW

C. Transceiver Sensitivity


- No enough link margin?
 - Denied**
- Sensitivity was reverified using RF shield box
 - Sensitivity was -99dBm (BIRDS5-S)
 - Similar to anechoic and short range test results
- Link Budget (Uplink) was calculated
 - **There is enough link margin**



Satellite	Link Margin					
	10° Elevation	20° Elevation	50° Elevation	70° Elevation	80° Elevation	90° Elevation
BIRDS-5FM	5.3 dB	8.6 dB	14.3 dB	15.9 dB	16.3 dB	16.43 dB
BIRDS-5S FM	4.3 dB	7.6 dB	13.3 dB	14.9 dB	15.3 dB	15.4 dB


A. Antenna Deployment: Dispatch Chamber

- ❑ Successful @ -30 degrees



- ❑ In orbit Antenna deployment was set to occur @ 17:20 JST satellites were not in eclipse
- ❑ Low temperature deployment failure **denied**

Position of the satellites (ISS TLE) when the antenna was supposed to be deployed



Mode: Real time Simulation

2022-12-02 17:21:00

5 minutes

Time: Local UTC

<<< < > >>>


5. Antenna Deployment Failed

B. Antenna Deployment: PETT Chamber


- TVT 1: unsuccessful
 - Wrong FM code
 - Connectivity problem

- TVT2: unsuccessful
 - Battery Damaged

- TVT3: Partial deployment**
 - EM battery used




Partial deployment



Pett Chamber Test

C. Antenna Deployment: Clean Room


- Done between TVT2 and TVT3
- Partial and full success



- ❑ TVT3 partial deployment (blocked by PETT Chamber)
 - A thermal ball was formed





- FM code, CW verified, normal operation
- Clear memory.
- SAT voltage measured at 3.61V
- SAT chattering testing then turn on
- No deployment, no CW after 35 mins
- Place into sun simulator at 36 mins
- Antenna deployed and CW at 1hr 07min,
however thread cut but antenna remained furled
- Deployment was blocked by satellite stand





Blocked Here

Antenna Deployment: Taken with High Speed Camera




Trial #	Orientation	Deployment Result	Remark
Trial 1	Vertical	success	
Trial 2	Vertical	success	
Trial 3	Horizontal	Success	
Trial 4	Horizontal	success	
Trial 5	Horizontal	Failed	Antenna was tightly tied







- Vacuum vs atmosphere temperature conditions



- The fishing wire ball from TVT is slightly bigger by a very small margin hence **denied**

D. TVT4 (Square chamber): Full deployment


- Vacuum Only
- Failure was therefore **denied**



Successful

E. Antenna deployment counter was set to a wrong value

- Deployed occurred as planned
- Deployment could not occur at voltages below 3V
- Even if no deployment, deployment counter increment
- Satellite did not wait for 24hrs to retry deployment and increment counter
- Unlikely**: Satellites were reset and memories flashed





Flash Memory Erase Confirmed

F. Reset PIC failed to activate the satellite

- Never observed on the ground therefore **unlikely**

G. Antenna deployment failed due to too much Kapton Tape.


- ❑ **Denied**- Antenna deployed




E. Antenna deployment was physically broken

- **Unlikely**- judged from delivery to JAXA


TAKA





ZIMSAT-1



PEARLAFRICASAT-1





BIRDS5-S Satellite

H. Fishing wire was stuck

- ❑ On points 1 and 2 it can get stuck under the antenna where the fishing wire crosses the antenna elements
- ❑ On points 3 and 4 the fishing wire can get pressed under the antenna guides when the antenna is stowed too tightly.
- ❑ This was known and was avoided at EM and FM
- ❑ **Denied:** Antenna deployed with proper tying method


Note: This was noticed when deployment was blocked by PETT chamber and satellite stand.




Test Conducted	Conditions	Chattering Confirmed	Sat Activated	Antenna Deployment	Note
FM Stage	<input type="checkbox"/> Low temperature (-30 deg) and atmosphere temperature	No	Yes	Yes	<input type="checkbox"/> 100 % success using dispatch chamber and in atmosphere temperature
Test in Clean room1	<input type="checkbox"/> Atmosphere temperature	Yes	Yes	Yes	<input type="checkbox"/> 98+ % successful
TVT1	<input type="checkbox"/> 3cycles <input type="checkbox"/> 2hr vacuum + high temperature	No	No	No	<input type="checkbox"/> Problem with connection cables <input type="checkbox"/> Wrong code
TVT2	<input type="checkbox"/> 3cycles <input type="checkbox"/> 2hr vacuum + high temperature	Yes	Yes	No	<input type="checkbox"/> Battery damaged <input type="checkbox"/> Low battery power
Test in Clean room1	<input type="checkbox"/> Atmosphere temperature	Yes	Yes	Partial	<input type="checkbox"/> Sun Simulator used Antenna blocked by satellite stand
TVT3	<input type="checkbox"/> 2 cycles <input type="checkbox"/> 1hr vacuum + high temperature	Yes	Yes	Partial	<input type="checkbox"/> PeTT chamber size blocked deployment
TVT4	<input type="checkbox"/> Vacuum only	No	Yes	Yes	<input type="checkbox"/> 100% successful
Test in Clean room1 (High speed camera)	<input type="checkbox"/> Atmosphere temperature	No	Yes	Yes	<input type="checkbox"/> 98% Successful

- ❑ Use shield box
- ❑ Compare the gains of :


Folded antenna



Partially deployment antenna (2 cases)



Full deployed antenna






Signal Power (dBm)	CASE1: Gain (dBi) (Small Partial Deployment)		CASE1: Gain (dBi) (High Partial Deployment)		CASE2: Gain dBi (Full Deployment)		Case 3: Gain (dBi) Folded	
	E-Plane	H-Plane	E-Plane	H-Plane	E-plane	H-Plane	E-plane	H-Plane
PTXlow &Att:39dB)	-36.10	-32.49	-28.09	-24.08	1.41	2.13		
PTXhigh (&Att:39dB)	-36.85	-32.25	-28.65	-23.65	1.44	2.25		
CW (19dBm)							-42.8	-45.38

CW downlink link budget

Considerations

Kyutech GS

- Partial deployment
- Satellite antenna gain, -23dBi
- Kyutech GS Antenna Gain, 22dB
- High Elevations +70°



Satellite	LINK MARGIN		
	70° Elevation	80° Elevation	90° Elevation
BIRDS-5S FM	-3.99 dB	-3.62 dB	-3.49 dB

Wakayama University GS

- Partial deployment
- Satellite antenna gain, -23dBi
- GS Antenna Gain, 30dB
- High Elevations +40°



Satellite	LINK MARGIN		
	40° Elevation	80° Elevation	90° Elevation
BIRDS-5S FM	1.02 dB	4.38 dB	4.51 dB



Antenna in folded state,

➤ *Communication with the satellites*

- ✓ Impossible with both BIRDS GS network and Wakayama University GS

Antenna in partial deployment

➤ *Communication with the satellites*

- ✓ unlikely with BIRDS GS network
- ✓ Likely with Wakayama GS

➤ Depends on the degree of partial deployment

Fully deployed antenna

Communication with the satellites

- ✓ Possible with all BIRDS GS network

A. TLE provided by JAXA (Almost same as ISS)

- No signal received

B. SATNOGS TLEs


- No signal received

C. TLE provided by NORAD

- No signal received

TLE differences

- Initially NORAD vs ISS vs JAXA TLEs
 - Very small difference
- Hence **unlikely**



Satellite position in orbit after deployment.

7. Others

A. Design Changes :

- The difference among BIRDS-3/BIRDS-4/KITSUNE/BIRDS-5
 - Changes in the EPS1 board of KITSUNE and FAB of BIRDS-5 from FAB of BIRDS-3
- Unlikely but open**- the changes were for improvements

B. Open Cases

- Kill Main flag observed in 1st TVT**
 - The flag went high**
- Antenna counter increment before 24hours reset**

- ❑ Three months Intensive investigations were conducted

- ❑ BIRDS5-S satellite was used for testing
 - Similar design to BIRDS 5 satellites in orbit

- ❑ Two major issues observed during TVT were
 - Battery failure
 - ✓ Unlikely because BIRDS5-S demonstrate satellite could operate under sunlight
 - Antenna deployment failure was observed due to
 - ✓ Tight tying of the antenna and it was already a known case that was taken care of
 - ✓ Creation of a thermal ball on fishing string, but no noticeable difference on the balls were observed in vacuum and room temperature
 - ✓ PETT chamber was small for full antenna deployment
 - ✓ However
 - ❖ Square chamber demonstrated that the antenna can deploy

- Flight software failure denied because LDT results were OK
- Human errors (Workmanship) denied as observed from the records
- Reset PIC is suspected as it occurred also in BIRDS4, however, BIRDS 5S could not reproduce the failure
- Suspicion remains about difference of production lots
 - Still inconclusive because we cannot reproduce the failure in orbit

OVERALL CONCLUSION

- No clear cause was identified to explain the failure of all the three satellites**

Lessons Learnt/ Areas for Design Improvements

1. Software change

- Add capability to COM Code to change CW duty cycle
- Change RESET PIC Code so watchdog timer clear is in the main code loop
- Add code to MAIN PIC for various mission executions (IMG-CLS, MULT-SPEC, PINO)
- Add code to MAIN PIC to automatically turn off missions after 15 minutes
- Changed command structure for all MAIN PIC and MISSION commands
- Add code for MISSION BOSS
- Change FAB code to increase resolution of ADCs

2. OBC/EPS board

Reset PIC design change options:


- Change PIC16F to PIC18F

- Have two PICS from PIC16F to 2 x PICS (16F + 18F) or 2x PICS(16F)

- Change PIC16F1789 to FUTABA PIC 16F877A (low power)

- Have two PICS and assign the PICS, one for monitoring and the other for power control

New Block Diagram of OBC/EPS: New Design Change



3. EPS change

- Consider using Li-Ion batteries, so far have good flight heritage
- Add small solar cells on antenna panel if space is available to aid satellite power

4. Structural design change

- Solder Jumper pin (J15) on FAB
- Use rail switch

5. Antenna Deployment Mechanism

- To increase the height of the antenna guides so that the fishing string will have more margin of passing under the antenna elements
- Do antenna deployment under vacuum conditions using thermal vacuum chamber

*Thank
you*