```
21:56:09          開始 MENGU CHO (Kyutech, Japan) : Please write your
affiliation and country in your name. Example, Mengu Cho (Kyutech,
Japan)
22:00:57          開始 MENGU CHO (Kyutech, Japan) : Please write your
affiliation and country in your name. Example, Mengu Cho (Kyutech,
Japan)
22:01:18          開始 Asia Habila : Asia Habila (Institute of Space Research
and
Aerospace(ISRA),Sudan)
22:01:38          開始 MENGU CHO (Kyutech, Japan) : In your name please. Not in
chat
message.
22:04:17          開始 T. Fuse (Kyutech, Japan) : you are encourage to write
questions in a
chatbox
22:25:03          開始 Edgar Mujuni(Kyutech, Japan) : Did you make your own APRS
firmware for the  ATMEGA QFP package? Or you used  the TT4 Byonics
Firmware?
22:30:31          開始 yama : Our satellite was reviewed by rev.D even after
JPAH's rev.E was
issued.
Did you change to rev.E during the review?
22:31:49          開始 Edgar Mujuni(Kyutech, Japan) : Did the Main PIC
Oscillator fail at satellite Turn ON? or in the middle of
operation?
22:33:52          開始 Edgar Mujuni(Kyutech, Japan) : That means COM PIC & TRX
continued to send CW even after main PIC failed to operate. is it
true?
22:42:17          開始 yama : thanks
22:46:37          開始 Edgar Mujuni(Kyutech, Japan) : What was the sensitivity
of your Radiometrix
TRX?
22:47:06          開始 syahrim - MYSA : Prof Cho. Is there a possibility to get
schematic for the payloads like the camera and
APRS?
22:51:55          開始 syahrim - MYSA : Thank you
22:57:37          開始 Marloun Sejera (Mapua, Philippines) : I believe that it
is better for the professionals to do the soldering of components to avoid
worksmanship error, especially
FM
23:01:39          開始 Marloun Sejera (Mapua, Philippines) : How many of f the
students worked with at least two Gardens
satellites?
```